

# One K-series

## ONE K56-3N (Clevo P150SM) - Downloads

On this page you find Drivers, Manuals and Biosupdates for your Gaming Notebook One K56-3N (Clevo P150SM).

**Please note, that you are updating the bios or ec-firmware at your own risk! Warranty exclusion: product damage caused by failed updates.**

### Bios Changelog:

#### System Bios 1.00.03

Solve "sometimes system hangs during POST" issue. Update ME to 1345. Refer to the content of readme.txt to update firmware.

#### EC firmware 1.00.04

Solve "can't enter CMOS setup by pressing F2 during fast start up procedure" issue. Refer to the content of readme\_EC.txt to update firmware

#### EC firmware 1.00.06

Add 3-zone light control for backlight keyboard.

Fn + keypad "7" key to control left zone light

Fn + keypad "8" key to control middle zone light

Fn + keypad "9" key to control right zone light

(need to update hotkey AP to 8.0124 or later).

Solve "sometimes plug on/off adapter will power on/off system" issue.

Refer to text file readme\_EC.txt to update firmware.

#### System Bios 1.00.06

Solve "system hangs by HD8970M VGA" issue. Refer to the content of readme.txt to update firmware.

#### System Bios 1.00.07

Set HDD type of SATA port 4 and port 5 toSSD type. Refer to the content of readme.txt to update firmware.

#### System Bios 1.00.09

Update ME firmware to 9.0.13.1402. Update VBIOS to 2177. Update RAID ROM to 12.7 PV. Update CPU micro code. Refer to the content of readme.txt to update firmware.

#### Bios 1.03.01 und Ec firmware 1.03.01

Add Winodows 8.1 support. Please refer to text files readme\_1st.txt, readme.txt and readme\_EC.txt to update firmware.

#### System Bios 1.03.03

Solve "sometimes system hangs during POST" issue. Solve "AMD 8970 VGA card causes Blue Death Screen problem" issue. Please refer to text file readme.txt to update firmware.

#### System Bios 1.03.04

# One K-series

Rename CMOS AMD VGA card product name. Refer to readme.txt to update firmware.

## System Bios 1.03.05

Solve “sometimes Win7 S4 resumes fail after CMOS UEFI setting change” issue. Refer to readme.txt to update firmware.

Unique solution ID: #2394

Author: Marcel Schürmann

Last update: 2018-06-13 12:45